

Adipns page 1

Adipns page 3

Adipns page 3

Adipns page 4


Google Maps



Imagery ©2016 DigitalGlobe, Map data ©2016 Google 100 ft

Google Maps

6/27/2006 10:14 AM





Rotten cross braces on bent # 4



Side view of the pier and the rail launch.



The second bent is missing its cross bracing and leaning hard. The third bent fell over causing the beams to span too far between support.

Continuation Page:



Restroom and facility sign for reference.



Pier looking at it from the opposite side of the creek



The Pier was closed off last summer because it was determined structurally unsafe.