



Describe spawning habitat: Very shallow water, gravel very silty

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: Mostly riffles and cascades with no pools.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: Stream is impacted by heavy surface runoff.

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: Cascade at mouth

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe: Due to nature of stream probably very little fish use.

Other species access and use:  Chum  Pink  Sockeye  Chinook  Trout

Describe: unknown

#### ENHANCEMENT OPPORTUNITIES: None


Project type:

Equipment access:


ADDITIONAL COMMENTS: There are three barrier culverts on this stream, but all are above a natural barrier and because stream is intermittent probably not worth repairing.

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References




Site id. code: SK9 RB1  
 Site name: Ebing cr  
 Scale: 1" = 25m  
 Observer(s): B. Barkdull  
 Legal location: NWS, T35N, R8E



NW8, T35N, R8E

Rm 56.9

sk9R31



1/12/97 Ebig of River 37, or 39  
0, 1m at River

31 m 1m 6% grade, and

corner, gully starts 10m

21m 1.5 m wide, grade

23m 1m wide steep cascade  
at 18" CC Road & route

Total Area

118 m<sup>2</sup>