

SITE NUMBER: B-L3-05
LOCAL NAME: Unnamed
WRIA: 20.0234C

NORTH COAST OFF CHANNEL SITE INVENTORY DATA

RIVER SYSTEM: Bogachiel **DATE:** 4/11/89 **OBSERVER:** Nettnin

CHANNEL TYPE: Lower end of a valley wall tributary

TRIBUTARY TO: Bogachiel River - 20.0162

SITE LOCATION: L.B. @ River mile - 9.6 (WDF)

LEGAL DESCRIPTION: SW1/4 S18 T28N R13W

| | UPPER END | LOWER END | RIVER TEMP |
|---------------------------|------------------|------------------|-------------------|
| <u>WATER TEMP:</u> | 44 F | 44 F | 43 F |

FLOW (CFS): 0.5 - 1.0 2 - 3

SUBSTRATE TYPE: Silt and silty gravel.

SITE SIZE: **Length-** 110 -120 m
Width- Surface = 4 to 5 ft
Channel = 5 to 6 ft
Depth- 6 to 8 inches

WATER SOURCE: Valley wall tributaries.

DIRECTIONS TO SITE: Heading north on Hwy 101 turn left just beyond MP 185 onto the G-2000. Follow the G-2000 approx. 6 miles until coming to the G-2600. Continue on the G-2000. Bear right at the Y in the road about 1 mile beyond the G-2600. Hike off the end of the road (NW 1/4 of the NW 1/4 of Sect 19, T28N, R13W) and down the hill in a NE direction (N 60 E) until coming to the channel or river (see site direction and B-L3 overview maps).

FISH ACCESS AND CURRENT USE: No fish were observed. It appears, however, that fish should have unrestricted access to the channel. The left bank tributaries to B-L3-05 all have plunges before entering the channel and appear to offer very little coho rearing habitat.

FLOODING POTENTIAL: Low.

LANDOWNER: Unknown at this time. Probably ITT Rayonier.

COMMENTS & RECOMMENDATIONS: A small valley wall trib feeds the upper end of B-L3-05. Two larger valley wall tribs enter the channel further downstream. The channel enters the river at a small back eddy on a glide. It appears to have good fish attraction potential, however, due to amount of flow. It has been very rainy lately and is currently raining, therefore flows appear very healthy at present. Should probably revisit this site during a winter dry spell. A beaded channel might be beneficial along the upper reach of B-L3-05. Channel has poor access for machinery and personnel.

DATE: 3/21/90

OBSERVER: King, Nettnin

Flow in this trib. was between 1/4 - 1/2 cfs. Some erosion has taken place since I surveyed the channel. Still not much habitat available.

Bogachiel River
Overview map
Site: B-13
Russo 7/97



