CROSS SECTION VIEW 1 - Site 2



materials = Dirt - 100 yds
Some Rock - 2 yds

Fill Replaced on top of Levee and about 1 Foot Below Levee at Eroded at north and south side of tide gate.

8/23/10

MADAMBA/Emrich

SLICE - CROSS SECTION - Site 2
VIEW #2



BASE OF DIKE INTACT

8/23/10
MADAMBA/EMRICH

EAGLE VIEW

VIEW # 3 - Site 2

Madamba / Emrich
8/23/12