SITE NUMBER: H-L8-07
LOCAL NAME: Unnamed
WRIA:
*This channel has not been assigned a WRIA number due to site is an overflow channel

NORTH COAST OFF CHANNEL SITE INVENTORY DATA

RIVER SYSTEM: Hoh River **DATE:** 8/25/87 **OBSERVER:** Young/Nettnin

CHANNEL TYPE: Overflow

TRIBUTARY TO: Hoh River (H-L8-06)

SITE LOCATION: LB @ River Mile- 18.8-19.3 (RM?)

LEGAL DESCRIPTION:

	UPPER END	LOWER END
WATER TEMP.:	53°	53°
DISSOLVED OXYGEN:		
AIR TEMP.:	68°	66°
FLOWS (CFS):	Dry	0.25

SUBSTRATE TYPE: Rubble, gravel, sand.

SITE SIZE: **Length-** Main channel = 615 m. Side channel = 150 m
Width- 20-30 ft
Depth- Mostly dry. Pools in lower section to 3 ft.

WATER SOURCE: Groundwater. Overflow from river in winter.

DIRECTIONS TO SITE: See map for H-L8 area.

FISH ACCESS AND CURRENT USE: Fish access is unrestricted. Lots of coho present in lower 150 m of channel. Dry channel above that point.

FLOODING POTENTIAL: Moderate to high.

LANDOWNER: Unknown at this time.

COMMENTS & RECOMMENDATIONS: The upper end of this channel diverges from the river at mile 19.3. It carries overflow water to channel H-L8-06 which currently is the lower end of Elk Cr. This channel appears to carry a great deal of water during winter flows.

Site: H-L8

Map B

H-L8-2
H-L8-6
H-L8-7
H-L8-8



Site : H-L8

Overview Map