SITE INFORMATION

Site Identifier : SK13LB3
Site Name :
WRIA : 03.1340X
Region : NS
Trib to : 03.1340
River Mile : 3.00
River System : Skagit R
Legal Description : NW1/4S32T35NR10E
County : Skagit
Habitat Type : slough

Landowner Type : Private
Landowner Name : Crown Pacific
Address :
Address2 :
City : Hamilton
State : Wa
Zipcode :
Phone :

Coordinates
East: 1,748,326.24 **North:** 1,150,322.71

Directions :
Take highway 20 to Rockport, take a right on highway 530 and cross the Skagit, go a mile and take a left on the Rockport-Cascade highway. Follow this road and take the second left on the Martin ranch road then a left towards Barnaby slough. You will cross Harrison slough, park at the barrel screen. The site is located 200' upstream on the right bank.

Area Overview :
Site is a shallow swale that is seasonally flooded and drains via a narrow channel into Harrison slough.

Field Survey Information

Date : 3/1/95 **Observer :** Barkdull **Survey Type :** initial

HABITAT INFORMATION

Water Source: ( ) Spring (x) Groundwater ( ) Surface runoff

Flow: (x) Intermitent ( ) Year-round

Estimated Flows (cfs): Lower end: 0.2
Upper end: 0

Water Temperature(C): Lower end:
Upper end:

Receiving Water Temperature (C):

Other Observations: Water is tannic in color.

Site Area Measurements: ( )Indirect (x) Direct ( ) Combination
Widths: Channel:2 Ponds: 11 Wetlands:
Depths: Channel:0.1 Ponds: 0.5 Wetlands:
Total length (includes ponds and wetlands): 485

Total existing habitat area (est. m2): 4452

Spawning area:	Mainstem:0	Tribs:	Total:0
Impounded area:	Mainstem:4218	Tribs:	Total:4218
Other rearing area:	Mainstem: 234	Tribs:	Total:234
Unaccessible habitat:	Mainstem:	Tribs:	Total:

Spawning habitat conditions: (x) None ( ) Poor ( ) Fair ( ) Good ( ) Exellent

Describe spawning habitat:

Rearing habitat conditions: ( ) None ( ) Poor ( ) Fair (x) Good ( ) Exellent

Describe pond and other rearing habitat:Site is mostly a brushy swale that fills in winter with water. The lower end is a narrow well defined channel with a silty bottom

Describe unaccessible habitat:

Wetland type: ( ) Bog ( ) Marsh ( ) Scrub-shrub ( ) Forested

Describe:

Flooding potential: ( ) Low (x) Medium ( ) High

Describe: From films I have seen of the 1990 flood it appears flood water moved down this channel.

FISH INFORMATION

Site entry condition: ( ) Poor ( ) Fair (x) Good

Describe:Fish have direct access from Harrison.

Coho access and use: Juvenile (x) Unknown ( ) None ( ) Poor ( ) Fair ( ) Good
Adult (x) Unknown ( ) None ( ) Poor ( ) Fair ( ) Good

Describe: This site is physically accessible to coho from Harrison Slough.

Other species acces and use: ( ) Chum ( ) Pink ( ) Sockeye ( ) Chinook (x) Trout

Describe:Trout use is possible but unknown.

ENHANCEMENT OPPORTUNITIES: The lower 100 meters or so we may be able to add some spawning habitat.

Project type:Gravel addition

Equipment access:Good

ADDITIONAL COMMENTS: There is probably flow from this site in the late fall to late spring time period, and completely dries up in summer. A 12" culvert and an abandoned log road crossing is located at 83 meters from the mouth

ATTACHMENTS AVAILABLE

(x) Aerials ( ) Sketch (x) Maps ( ) Spawning Surveys ( ) Juvenile Trapping
( ) Other References



3/1/95 Harrison slough to slough

465	At corner of Harrison upper. 2m avg width
402	At culvert ¼m wide, 12" round
362	10m slough opens up
235.	Avg. width 12m, shallow, murky
0.0	End. Intermittent Beyond

Harrison trib. SK13LB~~8~~3