SITE NUMBER: WD-L2-07
LOCAL NAME: Unnamed
WRIA:

NORTH COAST OFF CHANNEL SITE INVENTORY DATA

RIVER SYSTEM: W.F. Dickey **DATE:** 3/26/93 **OBSERVER:** Mosley

CHANNEL TYPE: Terrace Tributary

TRIBUTARY TO: W.F. Dickey

SITE LOCATION: LB @ RM: 14.4 (DNR Photo)

LEGAL DESCRIPTION: NW ¼, NW ¼, Sec. 9, T29N, R14W

	UPPER END	LOWER END	RIVER TEMP
WATER TEMP:	5.5° C	5.5° C	7.0° C
FLOW (CFS):	0.5	1.0	

SUBSTRATE TYPE: Gravel/Cobble/Clay

SITE SIZE: **Length-** 800 m
Width- Water surface = 0.5 - 2.0
Channel = 1.0 - 3.0
Depth- 20 - 30 cm **Max-** 60 cm

WATER SOURCE: Springs, surface runoff

DIRECTIONS TO SITE: Head north from Forks on HWY 101 about 3.1 mi. Turn left (west) about 0.1 mi. beyond MP 195 on D-2000. Proceed west on the D-2000 for 6.35 mi. to the D-2600. Turn left on the D-2600 and proceed 2.1 mi. and turn right on the D-5200. Proceed 1.0 mi. on the D-5200 then turn left on D-5230. Proceed 0.3 mi. down D-5230 road and park where culvert has been pulled out of this channel. This point is about 400 m upstream from the mouth of this stream.

FISH ACCESS AND CURRENT USE: There appears to be an impassable debris jam 60 m up from the mouth, however one school of about 6 to 12 yearling coho were observed immediately upstream from this point. No other fish were seen above this point.

FLOODING POTENTIAL: The lower 100 m or so of this stream is prone to flooding.

LANDOWNER: ITT Rayonier/DNR

COMMENTS & RECOMMENDATIONS: This stream has:
- Good egress to the river.
- Runs through 2nd grow hemlock in lower 370 m. Runs through recent clearcut unit above this point.
- Has a moderate gradient with gravel/cobble bottom composition.

This stream could be characterized as a small, moderate gradient terrace trib with little rearing potential. It has some spawning potential in the lower 200 m.

Recommend: (moderate priority)
- Remove debris jam near mouth.

DATE: 10/23/97 **OBSERVER:** Nettnin

It was observed on this date that the debris jam located near the mouth has washed out and is no longer a problem.


RIVER: W.F. DICKEY
AREA: WD-L2
CHANNEL: WD-L2-7
WD-L2-8
DATE: 3-93
MINUSCULE FLOWS- CHANNEL LOADED w/ STUMPS, DEBRIS & BLOWDOWN ABOVE THIS POINT
3-5 m BANK
UNSURVEYED
3-5 m BANK
3 m BANK
400 m
BANK
WEST FK. DICKEY
4m BANK
6m BANK
60m
240m
3 M
4 m BANK
7M
WD-L2-7
3m BANK
3m BANK
WD-L2-8
D-5230
D-5200


RIVER: W.F. DICKEY
AREA: WD-L2
AREA MAP
WD-L2
Dickey
River
Fork
Wentworth Lake
Boat Ramp
Bridge out
Mile 15
Mile 10
I-90
I-91
D-2600
D-5280
I-90A
I-91A
I-91B
AWD
258T
182T
290T
151T
115T
222T
245T
213T
318T
135T
138T
142T
283T
110T
145T
140T
144T
158T
155T
150T
98T
215T
151
402
573
Squa


WEST FK. DICKEY
AREA L-2
OVERVIEW MAP
3/93
WD-L2-7
D-5230
WD-L2-8
WD-L2-6
WD-L2-5
20.0141
20.0142
WD-L2-04
WD-L2-3
WD-142L-01
D-2600
DICKEY
FK.
WEST
20.0137
D-5200
WD-L2-2
WD-L2-1
LAKE WENTWORTH
N
S