

SITE NUMBER: D-L1-01
LOCAL NAME: Unnamed
WRIA:

NORTH COAST OFF CHANNEL SITE INVENTORY DATA

RIVER SYSTEM: Dickey **DATE:** 11/08/90 **OBSERVER:** Nettnin

CHANNEL TYPE: Valley Wall Trib.

TRIBUTARY TO: Dickey River (20.0097)

SITE LOCATION: L.B. @ River Mile: 0.4 (WDF)

LEGAL DESCRIPTION: NE1/4 S22 T28N R15W

	UPPER END	LOWER END	RIVER TEMP
<u>WATER TEMP:</u>	47 F	47 F	48 F
<u>FLOW (CFS):</u>	0.2 - 0.5	0.2 - 0.5	

SUBSTRATE TYPE: Silt and clay

SITE SIZE: Length- 70 m (Mouth to falls)
Width- Surface = 15 cm - 60 cm Channel = 0.6 m - 1.0 m
Depth- 15 cm - 25 cm

WATER SOURCE: Valley Wall Trib. Springs & marsh on upper terrace.

DIRECTIONS TO SITE: Head north from Forks on Hwy 101. Turn left just beyond mp 193 (1.0 mile north of Forks) onto La Push Rd. Proceed west on La Push Rd about 7.8 miles to Three Rivers Resort then turn right onto the Mora Rd. Continue west on the Mora Rd., past the Olympic National Park guard station, to the Dickey River Bridge. Park at the recreational parking area and walk up stream along the left bank of the Dickey River to the first small trib. (D-L1-01).


FISH ACCESS AND CURRENT USE: Fish have unrestricted access to the lower 70 m of D-L1-01 (i.e. mouth to 3 m falls). No fish were observed.


FLOODING POTENTIAL: Backwater flooding appears likely along the entire lower reach of the channel (i.e. the lower 70 m, mouth to falls).

LANDOWNER: O.N.P.

COMMENTS & RECOMMENDATIONS: There is a small amount of short term, winter rearing habitat in the lower 70 m of D-L1-01. The small pool at the base of the falls could be enlarged and/or deepened by use of a control. This would create a refuge bay area that could enhance the short term rearing capability of the channel.

River: Dicker
 SITE: D-LI
 Overview map
 Date 12/14/90





RIVER: DICKY
SITE: D-LI
CHANNEL: D-LI-1
LOCAL NAME: Unnamed Trib
Map date: 11/14/99

