

SITE INFORMATION

Site Identifier : BA1LB2 **Landowner Type :** Federal
Site Name : **Landowner Name :** USFS
WRIA : 03.1774X **Address :**
Region : NS **Address2 :**
Trib to : Bacon Cr **City :**
River Mile : 3.60 **State :**
River System : Bacon Cr **Zipcode :**
Legal Description : SE1/4S6T36NR11E **Phone :**
County : Skagit
Habitat Type : overflow channel

Directions :

Take Highway 20 past Marblemount to Bacon creek and turn left on the Bacon creek road, go 3 miles to the second road to the left. This road will dead end at a culvert washout. Follow the remains of the road to the creek and the site is located five hundred feet upstream on the left bank of a side channel. You will need the map.

Area Overview :

Site is a small, very floody overflow channel to Bacon Creek that provides a little bit of rearing good rearing habitat for coho.

Field Survey Information

Date : 10/27/97 **Observer :** Barkdull **Survey Type :** initial

HABITAT INFORMATION

Water Source: Spring Groundwater Surface runoff

Flow: Intermittent Year-round

Estimated Flows (cfs): Lower end: 0.1
Upper end: 0

Water Temperature(C): Lower end: 8.5
Upper end: 8.5

Receiving Water Temperature (C): 8

Other Observations:

Site Area Measurements: Indirect Direct Combination

Widths: Channel: 0.5 Ponds: Wetlands:

Depths: Channel: 0.1 Ponds: Wetlands:

Total length (includes ponds and wetlands):33

Total existing habitat area (est. m2): 13.3

Spawning area: Mainstem: 0 **Tribs:** **Total: 0**

Impounded area: Mainstem: **Tribs:** **Total:**

Other rearing area: Mainstem: 13.3 **Tribs:** **Total: 0**

Unaccessible habitat: Mainstem: **Tribs:** **Total:**

Spawning habitat conditions: None Poor Fair Good Excellent

Describe spawning habitat:

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: There is a small amount of low gradient, shallow, sandy bottomed channel.

Describe inaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe:

Flooding potential: Low Medium High

Describe: This is an extremely floody site and is in danger of becoming part of the side channel it enters.

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: Site enters an active side channel of Bacon Creek

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe: Coho juveniles were observed on the day of the survey.

Other species access and use: Chum Pink Sockeye Chinook Trout

Describe: There is probably some trout use of the site

ENHANCEMENT OPPORTUNITIES: None

Project type:


Equipment access:


ADDITIONAL COMMENTS: Please see BA1LB1

ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References

Site id. code: BA1LB2
Site name:
Scale: 1" = 10m
Observer(s): B. Barkdull
Legal location: SE6, T36N, R11E





614 615 616 R11E 25' 617 618
INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1989

SCALE 1:24 000



10/27/47 Trib to Brown, LB, Just
below Zunder - See who he did
"twist" tub

00 0.7 47° Oil ch
25 0.5 down to a truck
LB trib 2m, 0.4
33 oil end.

Very floody, may soon
get eaten by Brown or

13.3 m²

BAI LB2

