

SITE NUMBER: CW-R11-01

LOCAL NAME: Unnamed

WRIA:

NORTH COAST OFF CHANNEL SITE INVENTORY DATA

RIVER SYSTEM: Clearwater **DATE:** 7/7/88 **OBSERVER:** Nettin

CHANNEL TYPE: Lower end of a small valley wall trib

TRIBUTARY TO: Clearwater River (21.0024)

SITE LOCATION: River mile - 27.2 R.B.

LEGAL DESCRIPTION:

	UPPER END	LOWER END
<u>WATER TEMP.:</u>	48 F	48 F (River = 49 F)
<u>AIR TEMP.:</u>	50 F	50 F
<u>FLOW (CFS):</u>	0.1	0.1

SUBSTRATE TYPE: Silt, gravel and some rubble.

SITE SIZE: Length- 100 m
 Width- 2 - 3 ft
 Depth- 1 - 3 inches.

WATER SOURCE: Springs, valley wall trib.


DIRECTIONS TO SITE: Head north on Hwy 101. Turn right 0.9 mi. beyond mile post 146 onto the Clearwater Rd. Proceed north 4.5 miles until coming to mile post 25.5 (the first in a series of descending half mile markers). Stay on the mainline. Turn right between MP 11.5 and 12.0 (C-2000) just before coming to the Clearwater Correction Center. Proceed 3.5 miles then turn right onto the C-2017. See site direction and overview maps.

FISH ACCESS AND CURRENT USE: 0+ coho are using the lower end of CW-R11-01. Some small debris piles and a 6 inch falls restrict fry access but should not restrict pre-smolt movement. Enters into a nice back eddy at moderate flows. Present flow goes inter-gravel at mouth.

FLOODING POTENTIAL: Low. Some backwater flooding may occur.


LANDOWNER: Unknown at this time. Probably DNR.

COMMENTS & RECOMMENDATIONS: CW-R11-01 does not appear to have very heavy winter flows. A beaded channel may be possible here. Poor access to the site greatly restricts the possibility of habitat improvements. Machine access does not appear feasible.



Clearwater River
Site: Cw-R11
Channel Cw-R11-d1

N →



Clearwater River

Site: CW-R11, CW-L11

Over view Map

mod: 5/19/97

Note: The eastern third of the map has been compressed. Note river mileages.

(MC)


15 MINUTE SERIES (TOPOGRAPHIC)

124° 00' R. 10 W. 424

418 5' 420 421

Clearwater River

Site: CW-R11



5283