

SITE INFORMATION

Site Identifier : EN1LB1 **Landowner Type :** Private
Site Name : **Landowner Name :**
WRIA : 03.0230X **Address :**
Region : NS **Address2 :**
Trib to : EF Nookachamps Cr **City :**
River Mile : 3.50 **State :**
River System : EF Nookachamps Cr **Zipcode :**
Legal Description : NW1/4S19T34NR5E **Phone :**
County : Skagit
Habitat Type :

Directions :

From Highway 20 in Sedro-Woolley take Highway 9 south to Clear Lake, turn left on the Beaver Lake road. Follow past Beaver Lake approximately 3 miles to a sharp ninety degree corner with a driveway and bridge to the right. Park, the site is in the field on the opposite side of the road.

Area Overview :

Site is a wall-based channel that is in the middle of a cow pasture. The site has been very abused by cattle, and probably gets very little fish use because of its degraded condition.

Field Survey Information

Date : 10/26/99 **Observer :** B. Barkdull **Survey Type :** initial

HABITAT INFORMATION

Water Source: () Spring (x) Groundwater () Surface runoff

Flow: () Intermittent (x) Year-round

Estimated Flows (cfs): Lower end: 0.01
Upper end: 0

Water Temperature(C): Lower end:10
Upper end:

Receiving Water Temperature (C): 7.5

Other Observations:

Site Area Measurements: () Indirect (x) Direct () Combination
 Widths: Channel:0.5 Ponds: Wetlands:3.5
 Depths: Channel:0.1 Ponds: Wetlands:0.2
 Total length (includes ponds and wetlands):410

Total existing habitat area (est. m2):1246

Spawning area:	Mainstem:0	Tribs:	Total:0
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem:1246	Tribs:	Total:1246
Unaccessible habitat:	Mainstem:	Tribs:	Total:

Spawning habitat conditions: None Poor Fair Good Excellent

Describe spawning habitat:

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: The lower end of the site has been ditched to increase drainage, most of the site is a wetland dominated by Canary grass with Cattails in the upper end. The site in general is very abused by cattle and is in such poor condition very little fish use probably takes place.

Describe inaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe: See above.

Flooding potential: Low Medium High

Describe: Site is underwater during moderate flood conditions in the E.F. Nookachamps. During floods the Skagit River inundates all of the lower Nookachamps valley.

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: Fish have direct access to the site, flows may limit access at times.

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe: Fish access and use is unknown

Other species access and use: Chum Pink Sockeye Chinook Trout

Describe: Trout use is possible

ENHANCEMENT OPPORTUNITIES

Project type: Fencing and revegetation


Equipment access: Good

ADDITIONAL COMMENTS The site is not a high priority site for restoration but could be made more fish friendly with a little TLC.

ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References

wet
pasture



Site id. code: EM1 LB1
Site name:
Scale: 1" = 75m
Observer(s): B. Barkdull
Legal location: NW 19, T34N, R5E

10/26/99 Trub to E. Fork Nade

Trub 53, Mauston 47°

0.0 0.5 tracks of flow

11 0.3 Ditched, at fence

56 6.5 } Ditched, very abused by cattle
160 8.0 } Canary grass

400 ^{2.0} wetland mostly various stuff

last 300m cattails

ENVILBI

Rm 3.5

Rm. 19 T34, R5

Day

||||| ||||| |||||

Ditch 410

160

|||||

160

SL

Foot

