

Spawning habitat conditions: None Poor Fair Good Excellent

Describe spawning habitat: Habitat is small riffles and pools with clean, excellent sized gravel.

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: Pools are small with good cover throughout.

Describe inaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe:

Flooding potential: Low Medium High

Describe: Site appears very stable, and mostly above all but the most serious events from Pilchuck Creek.

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: A large back eddy is at the mouth

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe: Site is obvious used extensively, newly emergent coho fry were present in extremely large numbers throughout the site.

Other species access and use: Chum Pink Sockeye Chinook Trout

Describe: Cutthroat trout use is assumed.

ENHANCEMENT OPPORTUNITIES: None

Project type:


Equipment access: Poor

ADDITIONAL COMMENTS

ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References

Site id. code: PIZ RB20
Site name:
Scale: 1" = 10m
Observer(s): B. Barkdull
Legal location: SW16 T32N R5E



4/30/02 Verb to Pitlock on
 on R Bank above PTF Access 007A
 River 51°, stream 52° Cole post
 0.0 0.5 Big Eddy at mouth
 42 1.2 at Big Stamp many log
 mostly white, all good gravel
 in Pitlock 0.0
 49 All diametric range
 73 1.2 starting Bed into 2nd grade
 100 1.2 Entering gully gully steeper
 133 1.2 falls

All sporadic to 73m

73 to 100 50% time steep Big
above

PI 2 RB 20

7/1/02
 10/1/02

133m ~~216~~

