

Total existing habitat area (est.): 100 m²

Spawning area: 00 m²

Impounded area: 00 m²

Other rearing area: 100 m²

Spawning Habitat conditions: (X) None () Poor () Fair () Good () Excellent

Describe spawning habitat: NA

Rearing habitat conditions: () None () Poor (X) Fair () Good () Excellent

Describe pond and other rearing habitat:

- Cover is provided by small woody debris and detritus.
- Emergent vegetation is present.
- No RMZ. Shade is provided by brush and 10 - 15 year old conifer
- Stream channel is shallow and narrow.

Describe unaccessible habitat: NA

Describe wetland: () Bog (X) Marsh () Scrub-shrub Wetland () Forested Wetland

- Small (5 - 6 m wide), soft, mucky area covered with water parsley and other aquatic vegetation.
- Shallow channel.
- There are wetland characteristics where the stream flows through the flood plain of Beaver Creek.

Flooding potential: (X) Low () Medium () High

Fish Information:

Site entry condition to Beaver Creek (20.0324): () Poor () Fair (X) Good

- Good entrance conditions when flows are higher.
- Egresses into a large back eddy.

Coho use:

- Juvenile- (X) Unknown () None () Poor () Fair () Good
- Adult- () Unknown (X) None () Poor () Fair () Good
- Fry were present in small numbers.

Other species use: () Chum () Pink () Sockeye () Chinook (X) Trout

- No trout were identified. It is assumed they use this channel.

Habitat Improvements:

Enhancement opportunities:

- Possible project type:
- Maintain the integrity of the channel.


Additional Comments:

- G.P.S. readings: Taken, but not recorded at present time.

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:

- () Aerials (X) Sketch (X) Maps () Culvert Report
- () Other references () Spawning surveys () Juvenile trapping () Fishway Report




RIVER: SOL DUC

TRIB: Beaver Creek - 20.0324
AREA: S-R5
SITES: S-324L-07, S-324L-08
WRIA: 20.0324M, 20.0324O
NAMES: Unnamed

DATE: 6/00

S-324L-08
North from Forks to M.P. 203.9. Turn left onto SR 113 and follow for 2.0 mile. Turn left onto FS 100 road and go through the rock pit. Take the immediate left onto the FS 105 road and follow for 0.6 mile to a stream crossing. This is S-324R-05. Follow S-324R-05 to Beaver Creek. Cross to the left bank side, then walk downstream about 50 meters. S-324L-08 is located just above a log jam.



- Major Waters
- Numbered Tributaries
- Unnumbered Tributaries
- Road Access
- Previously Catalogued WRIA Numbers
- Currently Catalogued WRIA Numbers
- Site Numbers, Feature Names, etc.

RIVER: SOL DUC

TRIB: BEAVER CREEK
 WRIA: 20.0324
 AREA: S-R5

OVERVIEW MAP
 2000

1-209-X
 510.2
 Borrow Pit