

Spawning Habitat conditions: (X) None () Poor () Fair () Good () Excellent

Describe spawning habitat:

- NA

Rearing habitat conditions: () None () Poor () Fair () Good (X) Excellent

Describe pond and other rearing habitat:

- The channel is low in gradient.
- Instream cover is provided by some woody debris and by sedges which dominate the marsh area.
- The habitat is usable in the winter and early summer. It is unknown if it stays watered all year.
- Overhead cover is primarily a hardwood canopy and a brush understory.

Describe unaccessible habitat: NA

Describe wetland: () Bog () Marsh () Scrub-shrub Wetland (X) Forested Wetland

- The channel drains a small portion of a very large wetland.
- The wetland source is seeps and small springs.

Flooding potential: (X) Low () Medium () High

- The channel is susceptible to overbank storage from upper Beaver Creek.

Fish Information:

Site entry condition to S-324L-16: () Poor () Fair (X) Good

- The channel egresses into a deep slow moving reach.

Coho access and use:

- Juvenile- () Unknown (X) None () Poor () Fair () Good
- Adult- () Unknown (X) None () Poor () Fair () Good
- This channel is upstream of an anadromous barrier.

Other species access and use: () Chum () Pink () Sockeye () Chinook (X) Trout

- Fish were observed during the survey.

Habitat Improvements:

Enhancement opportunities:

- Possible project type:
- Maintain the integrity of the stream.
- Equipment access - None

Additional Comments: - G.P.S. egress location: East- 1,088,772 North- 1,036,517
End survey East- 1,088,872 North- 1,036,275

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:

- () Aerials (X) Sketch (X) Maps () Culvert Report
- () Other references () Spawning surveys () Juvenile trapping () Fishway Report

RIVER: SOL DUC


TRIB: Beaver Creek - 20.0324

AREA: S-R5

SITE: S-324L-16, S-324L-17, S-324L-18, S-324L-19

NAMES: Unnamed, Unnamed, Unnamed, Unnamed

DATE: 4/02



North from Forks to M.P. 203.9. Turn left onto SR 113 (Burnt Mountain Road). Follow for 4.8 miles to a wide spot off to the right side of the road, at the southerly end of the guardrail. Walk down and cross Beaver Creek. Follow a southerly bearing.

