

Describe spawning habitat:

- Spawning habitat is limited to resident trout due to small, patchy areas.

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat:

- This system is limited in rearing, and may be only utilized during small periods of time by coho.
- Cutthroat would be more likely to utilize the lower end of this system.
- There is a dense canopy of conifer, and cover from brush and woody debris.
- The upper end of the surveyed section of channel had boulders and large, old woody debris.

Describe unaccessible habitat:

- None

Describe wetland: Bog Marsh Scrub-shrub Wetland Forested Wetland

- None

Flooding potential: Low Medium High

Fish Information:

Site entry condition to (Eagle Cr- 20.0335): Poor Fair Good

- The channel has an open egress.

Coho access and use:

- Juvenile- Unknown None Poor Fair Good
- Adult- Unknown None Poor Fair Good
- Use by coho juveniles would be limited.
- The system is too small for utilization by adults.

Other species access and use: Chum Pink Sockeye Chinook Trout

- It is likely that cutthroat utilize the lower reach of this channel.

Habitat Improvements:

Enhancement opportunities:

- Maintain integrity of system.

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:

- | | | | |
|---|--|--|---|
| <input checked="" type="checkbox"/> Aerials | <input checked="" type="checkbox"/> Sketch | <input checked="" type="checkbox"/> Maps | <input type="checkbox"/> Culvert Report |
| <input type="checkbox"/> Other references | <input type="checkbox"/> Spawning surveys | <input type="checkbox"/> Juvenile trapping | <input type="checkbox"/> Fishway Report |

