

Total existing habitat area (est.): 37 m²

Spawning area: 0
Impounded area: 0
Other rearing area: 37 m²

Spawning Habitat conditions: (X) None () Poor () Fair () Good () Excellent

Describe spawning habitat:

- There is traces of gravel in the mud substrate.

Rearing habitat conditions: () None (X) Poor () Fair () Good () Excellent

Describe pond and other rearing habitat:

- This channel flows through a mix forest of alder and conifer with overhead cover of vine maple and brush.
- This channel is limiting due to it's size.
- This channel could offer some refuge during high river flows.
- Fry may utilize this channel during spring months.

Describe unaccessible habitat:

- None

Describe wetland: () Bog () Marsh () Scrub-shrub Wetland () Forested Wetland

- None

Flooding potential: () Low (X) Medium () High

- Channel would probably backwater during high river flows.

Fish Information:

Site entry condition to (Sol Duc River 20.0096): () Poor () Fair (X) Good

- Egresses into a braided, rocky river bend.
- There is both a small upstream and downstream eddy at the egress which provide slack water.

Coho access and use:

Juvenile- (X) Unknown () None () Poor () Fair () Good
Adult- () Unknown (X) None () Poor () Fair () Good

Other species access and use: () Chum () Pink () Sockeye () Chinook () Trout

- It is unknown but trout may utilize this channel.

Habitat Improvements:

Enhancement opportunities:

- No equipment access.
- Maintain integrity of channel.

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:


(X) Aerials	(X) Sketch	(X) Maps	() Culvert Report
() Other references	() Spawning surveys	() Juvenile trapping	() Fishway Report



RIVER: SOL DUC

AREA: S-L8
SITES: S-L8-03, S-L8-04
WRIA: 20.0344C, 20.0345C
NAMES: Unnamed, Unnamed

DATE: 4/97



RIVER: SOL DUC

AREA: S-L8

AREA MAP

DATE: Spring/97

