

**SITE INFORMATION**

**Site Identifier :** SA7RB5 **Landowner Type :**  
**Site Name :** **Landowner Name :**  
**WRIA :** 03.1095X **Address :**  
**Region :** NS **Address2 :**  
**Trib to :** 03.1095 **City :**  
**River Mile :** 0.10 **State :**  
**River System :** Sauk R **Zipcode :**  
**Legal Description :** NE1/4S25T32NR9E **Phone :**  
**County :** Snohomish  
**Habitat Type :** lower valley wall tributary

**Directions :**

In Darrington take the Sauk prairie road and cross the Sauk, Take the first gravel road to the right and follow 1.5 miles to 03.1095. Site is located 0.1 miles upstream.

**Area Overview :**

This is a small, high gradient surface stream that a few coho adults use in the lower end.

**Field Survey Information**

**Date :** 02/12/1996 **Observer :** Barkdull **Survey Type :** initial

**HABITAT INFORMATION**

**Water Source:**  Spring  Groundwater  Surface runoff

**Flow:**  Intermittent  Year-round

**Estimated Flows (cfs):** Lower end: 1.0  
Upper end: 1.0

**Water Temperature(C):** Lower end: 6  
Upper end: 6

**Receiving Water Temperature (C):** 6

**Other Observations:**

**Site Area Measurements:**  Indirect  Direct  Combination

**Widths:** Channel: 1.0 **Ponds:** **Wetlands:**

**Depths:** Channel: 0.1 **Ponds:** **Wetlands:**

**Total length (includes ponds and wetlands):** 39

**Total existing habitat area (est. m2):**

**Spawning area:** Mainstem: 10 **Tribs:** **Total: 10**

**Impounded area:** Mainstem: **Tribs:** **Total:**

**Other rearing area:** Mainstem: 39 **Tribs:** **Total: 39**

**Unaccessible habitat:** Mainstem: **Tribs:** **Total:**

**Spawning habitat conditions:**  None  Poor  Fair  Good  Excellent

Describe spawning habitat: An alluvial fan with small gravel changing to large gravel as you go upstream

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: Riffle habitat with very small pools.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: Out of Sauk river flood plain

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: Alluvium is shallow and may present problems at lower flows.

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe: Redds were observed on day of survey. juvenile use is probably very limited.

Other species access and use:  Chum  Pink  Sockeye  Res. Trout  Anad trout

Describe: Trout use possible but unknown.

ENHANCEMENT OPPORTUNITIES: None

Project type:


Equipment access:

ADDITIONAL COMMENTS: Total adult use is probably on the order of one or two redds a year.

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References

Site ID: SA7RB5  
 Date: 03.10.95  
 Scale: 1" = 10M  
 Observer(s): B. Barkdull  
 Legal location: NE25, T32N, R9E





2/12/96 Trib to 1095 (Sank r.) 41°  
0.0 Cascade 1 m wide bedrock  
28.0 1 m splitting channel, spawning below  
39.0 1 m main source of gravel for  
this fork of the creek  
41°

