



Describe spawning habitat: Graded spawning gravel was placed throughout most of the channel.

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: The site has very stable flows and low velocity. Channel is lined on the banks with large rock to provide cover and woody debris has been placed intermittently for cover. Two large "cover pools" were constructed for added rearing habitat.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: Site is on a moderately well protected river bench. Site is backwatered during high flows.

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: Fish have direct access from the original Illabot channel.

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe: Juveniles can be observed in large numbers throughout the channel. Adult use is very good, and is well documented.

Other species access and use:  Chum  Pink  Sockeye  Chinook  Trout

Describe: Adult Chum have been observed spawning in large numbers. Trout have been observed.

ENHANCEMENT OPPORTUNITIES: None

Project type:


Equipment access:

ADDITIONAL COMMENTS: Site was constructed in 2000

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References

Map Title



SKINLBS

