

SITE INFORMATION

Site Identifier :	SK2RB3	Landowner Type :	Private
Site Name :		Landowner Name :	
WRIA :	03.0278X	Address :	
Region :	NS	Address2 :	
Trib to :	Skiyou Slough	City :	
River Mile :	1.15	State :	
River System :	Skagit R	Zipcode :	
Legal Description :	SE1/4S21T35NR5E	Phone :	
County :	Skagit	Coordinates	
Habitat Type :	terrace tributary	East:	1,595,587.00 North: 1,161,488.00

Directions :
From the Hoehn Rd and Fruitdale Rd intersection in Sedro Woolley, go east 2.4 miles to the site.

Area Overview :
The landowner did not see this site as being fish habitat and did not like the idea of it being surveyed. There was no survey done. However there is nothing to stop fish from entering this site except maybe for water quality. This creek is classified as a type 3 on the DNR typing maps.

Field Survey Information

Date : 1/22/01 **Observer :** Olis **Survey Type :** initial

HABITAT INFORMATION

Water Source: Spring Groundwater Surface runoff

Flow: Intermittent Year-round

Estimated Flows (cfs): Lower end:
Upper end:

Water Temperature(C): Lower end:
Upper end:

Receiving Water Temperature (C):

Other Observations:

Site Area Measurements: Indirect Direct Combination

Widths: Channel:	Ponds:	Wetlands:
Depths: Channel:	Ponds:	Wetlands:
Total length (includes ponds and wetlands):		

Total existing habitat area (est. m2): unknown

Spawning area:	Mainstem:	Tribs:	Total:
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem:	Tribs:	Total:
Unaccessible habitat:	Mainstem:	Tribs:	Total:

Spawning habitat conditions: None Poor Fair Good Exellent

Spawning habitat conditions: None Poor Fair Good Excellent

Describe spawning habitat: unknown

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: unknown

Describe unaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe:

Flooding potential: Low Medium High

Describe: unknown

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: unknown

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe:

Other species acces and use: Chum Pink Sockeye Chinook Trout

Describe:

ENHANCEMENT OPPORTUNITIES


Project type:

Equipment access:

ADDITIONAL COMMENTS: Landowner said that the county biologist agreed with him in calling this creek non fish bearing. He did not like the idea of it being surveyed. It appears that there may be some water quality issues but there is no physical barriers to fish entering this site. This creek appears to be 1 meter wide, shallow and intermittent.


ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References



(SEDRO-WOLLEY SOUTH)

SCALE 1:24 000




SKZ RB3

INTERIOR-GEOLOGICAL SURVEY, RESTON, VIRGINIA
563 564000m. E

ROAD CLASSIFICATION

Primary highway, hard surface
Secondary highway,
Light-duty road, hard surface
improved surface



P67906

P40082

P67970

P67971

28

P40083

P99661

P110125

8

P40086

P112822

P40085

10

17

S/P 35-89
TRACT 29
TRACT NO. 1
PEAVEY'S ACREAGE
TRACTS NO. 1 & 2

2

28

P96425

1

P67907

P67986

P67987

P40087

P116625

P40088

P67988

20

40

P67921

19

UNOPENED COUNTY ROW

ABANDONED BONNEVILLE POWER ADMINISTRATION ROW

COAL CREEK

COAL

HOEHN ROAD

SKIYOU SLOUGH

UNOPENED COUNTY ROW

LOT - 1

29

P68000

P68001

LOT - 2

P40060 (3/5 INTEREST)
P109158 (2/5 INTEREST)

P67997

30

P67997

31

P67998

P67998

32

LOT - 5

LOT - 6

P40063

0082

LOT - 8

P40071

HOEHN ROAD

LOT - 7

P40069

P40085

P40067

P40086

P40065

P998317

189