

**SITE INFORMATION**

<b>Site Identifier :</b>	SK3LB1	<b>Landowner Type :</b>	
<b>Site Name :</b>		<b>Landowner Name :</b>	
<b>WRIA :</b>	03.0281X	<b>Address :</b>	
<b>Region :</b>	NS	<b>Address2 :</b>	
<b>Trib to :</b>	Gilligan Cr	<b>City :</b>	
<b>River Mile :</b>	0.10	<b>State :</b>	
<b>River System :</b>	Skagit R	<b>Zipcode :</b>	
<b>Legal Description :</b>	NW1/4S35T35NR5E	<b>Phone :</b>	
<b>County :</b>	Skagit	<b>Coordinates</b>	
<b>Habitat Type :</b>	lower valley wall tributary	<b>East:</b>	1,603,566.10 <b>North:</b> 1,153,688.76

**Directions :**

Take Highway 20 to Sedro Woolley, turn south on Highway 9 and cross the Skagit River. After crossing the Skagit take the South Skagit Highway toward Day Creek. Gilligan Creek is located five miles from the turn off, the site is located just above the road.

**Area Overview :**

Site is a small steep surface stream which offers a short reach of mostly spawning habitat.

**Field Survey Information**

**Date :** 1/28/98 **Observer :** Barkdull **Survey Type :** initial

**HABITAT INFORMATION**

**Water Source:**  Spring  Groundwater  Surface runoff

**Flow:**  Intermittent  Year-round

**Estimated Flows (cfs):** Lower end:0.5  
Upper end:0.5

**Water Temperature(C):** Lower end:8  
Upper end:8

**Receiving Water Temperature (C):** 5.5

**Other Observations:**

**Site Area Measurements:**  Indirect  Direct  Combination

Widths: Channel: 1.5 Ponds: Wetlands:  
 Depths: Channel: 0.1 Ponds: Wetlands:  
 Total length (includes ponds and wetlands): 90

**Total existing habitat area (est. m2):**145

Spawning area:	Mainstem: 40	Tribs:	Total: 40
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem: 145	Tribs:	Total: 145
Unaccessible habitat:	Mainstem:	Tribs:	Total:

**Spawning habitat conditions:**  None  Poor  Fair  Good  Excellent

Describe spawning habitat: Gravel is unevenly sized with a high fines component.

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: Site is mostly riffles with almost no pool habitat.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: Site appears to suffer from extreme flows on freshets

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: Site enters just above the South Skagit Highway crossing at a steep riffle

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe:

Other species access and use:  Chum  Pink  Sockeye  Chinook  Trout

Describe: Trout use is assumed but unknown

ENHANCEMENT OPPORTUNITIES: None

Project type:

Equipment access:

#### ADDITIONAL COMMENTS

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References


Site id. code: SK3LBI

Site name:

Scale: 1" = 75 m

Observer(s): B. Barkdull

Legal location: NW 1/4 S35, T35N, R5E



20' culvert S. Skagit Highway

Am 0.1

19m  
30% gradient  
40m

78 m alluvial fan  
96 m

End of Access  
30% gradient


Gilligan cr


Steep Bank

Day cr. rd.

Steep

313501





1/23/98 Gilligan cr. trib

@ S. Skagit Hwy

0.0 1.0 Cascade, enters @ 20' culvert

19.0 1.5 3% gradient, window out

40.0 2.0 low gr. Nice gr.

78 1.5 at Alluvial fan 4% gr.

90 1.5 Pool of access, 30% gr.

Station 46, Gilligan 41

SK3 LBI

Rm 0.1

NW 35, T35N, R5E