

SITE INFORMATION

Site Identifier :	SK7LB4	Landowner Type :	
Site Name :		Landowner Name :	
WRIA :	03.0384BX	Address :	
Region :	NS	Address2 :	
Trib to :	03.0384B	City :	
River Mile :	0.60	State :	
River System :	Skagit R	Zipcode :	
Legal Description :	SW1/4S23T35NR7E	Phone :	
County :	Skagit	Coordinates	
Habitat Type :	lower valley wall tributary	East:	1,669,306.00
		North:	1,160,117.00

Directions :

Take Highway 20 to Sedro-Woolley, turn right on Highway 9 southbound and cross the Skagit River. Turn right on the South Skagit Highway and follow past Mill Creek. Take the first forest road to the right which is gated. Follow the road past where it crosses Savage Creek and stay to the left. The road crosses 03.0384B in approximately 0.4 miles. Park and walk upstream.

Area Overview :

Site is a small surface stream with a short anadromous reach that is 50% covered with logging slash.

Field Survey Information

Date : 5/29/01 **Observer :** Barkdull **Survey Type :** initial

HABITAT INFORMATION

Water Source: Spring Groundwater Surface runoff

Flow: Intermittent Year-round

Estimated Flows (cfs): Lower end:0.5
Upper end:0.5

Water Temperature(C): Lower end:8
Upper end:

Receiving Water Temperature (C): 8

Other Observations:

Site Area Measurements: Indirect Direct Combination

Widths: Channel:1.5 Ponds: Wetlands:

Depths: Channel:0.2 Ponds: Wetlands:

Total length (includes ponds and wetlands):36

Total existing habitat area (est. m2):54

Spawning area:	Mainstem:20	Tribs:	Total:20
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem:54	Tribs:	Total:54
Unaccessible habitat:	Mainstem:	Tribs:	Total:

Spawning habitat conditions: None Poor Fair Good Excellent

Describe spawning habitat: Gravel is of an appropriate size for coho and searun cutthroat and relatively free of fines.

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: Stream is a mix of pools and riffles with extremely thick brush lining the banks. Stream is littered with logging debris which does not appear to be a problem.

Describe unaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe:

Flooding potential: Low Medium High

Describe: Stream has been moderately affected by timber harvest in the watershed.

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: Access into the trib is excellent but a culvert on 03.0384B prevents juvenile access, and limits access for adults.

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe: Some coho use is presumed but was not observed.

Other species access and use: Chum Pink Sockeye Chinook Trout

Describe: One sea-run cutthroat redd was observed.

ENHANCEMENT OPPORTUNITIES: The culvert under the access road on 03.0384B is a 67% barrier.


Project type: Culvert replacement/removal

Equipment access: good


ADDITIONAL COMMENTS


ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References



Site id. code: SK7LB4
Site name:
Scale: 1" = 7m
Observer(s): B. Barkdull
Legal location: SW 1/4 S23, T35N, R7E





PUBLISHED BY THE UNITED STATES GEOLOGICAL SURVEY
 CONTROL BY USGS AND NOS/NOAA
 DERIVED FROM AERIAL PHOTOGRAPHS TAKEN 1983
 CHECKED 1986. MAP EDITED 1989
 PROJECTION LAMBERT CONFORMAL CONIC
 1000-METER UNIVERSAL TRANSVERSE MERCATOR ZONE 10
 10,000-FOOT STATE GRID Ticks WASHINGTON, NORTH ZONE



5/29/01 trib to Savage manhole

0. 1.0 47°

36 1.5 extremely brushy

patches of good grass

one road observed Scorpion?

50% of stream covered in

slash. End of line gradient

0.5 cfs

manhole 47°

sk7L04

Rm 0.8

SW 1/4 23 T35N R7E

X 1669306

Y 1160117

