



Describe spawning habitat:

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: Slow moving stream with some nice structured pools in it. Has heavy brush along the banks providing good cover.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: The first 100m was hit pretty hard by Nov. 95 flood event as river water came over the bank and deposited silt heavily along the stream bed and banks. Also, one of the intermittant side slope feeder tribs had a small blowout, depositing a load of gravel in the stream (210m).

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: There is a holding pool area just below the mouth of the stream.

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe:

Other species acces and use:  Chum  Pink  Sockeye  Res. Trout  Anad trout

Describe: No trout were observed during survey but system offers some trout habitat.

#### ENHANCEMENT OPPORTUNITIES

Project type:


Equipment access:


#### ADDITIONAL COMMENTS

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References

Site id. code: SUZ. 61  
Site name:  
Scale: 1" = 50m  
Observer(s): MICHAEL OLIS  
Legal location: NE 1/4 S10 T33N R10E







78m... MOST DAMAGE  
E SILTING CAME FROM  
THIS SWALE.

134m WW 1m RIFF  
- SMALL FLOOD CHANNEL  
ENTERS ON RB  
- BANKS ARE IN BETTER  
SHAPE, BUT SMALL AMOUNTS  
OF SILTING PRESENT

- SMALL AMOUNTS OF  
P-GRAVEL & SAND  
PRESENT W/ SUBSTRATE

181m WW 1m RIFF  
- MOSTLY P-GRAV. SUBSTR.  
- SMALL INT. STRAM ON LB

212m WW 6m POOL  
- SUBSTRATE COVERED W/  
LEAVES  
- WISE TAIL AND BERRY BUSHY  
ALONG BANKS  
- INTUITANT STRAM ON  
LB THAT HAD A LITTLE  
BLOW OUT.

286m WW 5m POOL  
- HVY BRUSH STANDING IN  
SLOW MOVING SHALLOW  
WATER  
- LIVER WORT & PIGGY  
BACK PLANTS PRESENT  
- SECTION @ VERY BASE  
OF STEEP HILL

410m WW 1.5m

- 75/25 P/R

- SLOW MOVING STREAM THROUGH HEAVY BRUSH
- ORGANIC - MUCH SMOKE
- @ END OF FISH ACCESS (LOG ACCESS)

480m WW 75m

- SLOW MOVING STREAM
- APPEARS TO BE INTERMITTANT AND FLOWS INTO THIS FLAT SHRUB-SHRUB MARSHY AREA

COMMENTS - NO SPAWN AVAILABLE

- HIGH FLOOD POT. FOR 1ST 100m.
- GRND WATER & SURFACE FED
- WALL BASE STEIN
- MANY PLACES WHERE WATER SEEPS OFF HILL
- REARING IS FAIR TO GOOD,