

**SITE INFORMATION**

**Site Identifier :** SU2RB2 **Landowner Type :** Federal  
**Site Name :** **Landowner Name :** USFS  
**WRIA :** 03.0710X **Address :**  
**Region :** NS **Address2 :**  
**Trib to :** Suiattle R **City :**  
**River Mile :** 7.00 **State :**  
**River System :** Suiattle R **Zipcode :**  
**Legal Description :** NW1/4S13T33NR10E **Phone :**  
**County :** Skagit  
**Habitat Type :**

**Directions :**  
 Take Forest Service # 26 road approximately 5.4 miles upriver to the edge of a clear cut. Hike down to river and site.

**Area Overview :**  
 A short wall base trib that offers small amounts of over winter rearing, but probably does not flow during summer months.

**Field Survey Information**

**Date :** 12/20/1995 **Observer :** Olis **Survey Type :** initial

**HABITAT INFORMATION**

**Water Source:** (X) Spring ( ) Groundwater (X) Surface runoff  
**Flow:** (X) Intermittent ( ) Year-round  
**Estimated Flows (cfs):** Lower end: 0.1  
 Upper end:  
**Water Temperature(C):** Lower end: 7  
 Upper end: 7  
**Receiving Water Temperature (C):** 5

**Other Observations:**

**Site Area Measurements:** ( ) Indirect (X) Direct ( ) Combination  
 Widths: Channel: 1m Ponds: Wetlands:  
 Depths: Channel: 10cm Ponds: Wetlands:  
 Total length (includes ponds and wetlands): 219m

**Total existing habitat area (est. m2):** 219  

Spawning area:	Mainstem:	Tribs:	Total:
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem: 219	Tribs:	Total:
Unaccessible habitat:	Mainstem:	Tribs:	Total:

**Spawning habitat conditions:** (X) None ( ) Poor ( ) Fair ( ) Good ( ) Excellent

Describe spawning habitat:

Rearing habitat conditions:  None  Poor  Fair  Good  Excellent

Describe pond and other rearing habitat: Slow moving, pooled stream with structure from fallen branches and trees. Has good cover from berry and other brush.

Describe unaccessible habitat:

Wetland type:  Bog  Marsh  Scrub-shrub  Forested

Describe:

Flooding potential:  Low  Medium  High

Describe: On high bench and was not affected by Nov. 95 flood event except for entry area. A big load of silt was deposited across the mouth of this system.

#### FISH INFORMATION

Site entry condition:  Poor  Fair  Good

Describe: There is a holding pool area just below the mouth, but this stream has to negotiate its way through the silt deposit from the recent flood event. This made the stream shallow and a little harder for juveniles to access.

Coho access and use: Juvenile  Unknown  None  Poor  Fair  Good  
Adult  Unknown  None  Poor  Fair  Good

Describe:

Other species access and use:  Chum  Pink  Sockeye  Res. Trout  Anad trout

Describe:

#### ENHANCEMENT OPPORTUNITIES

Project type:

Equipment access:

#### ADDITIONAL COMMENTS

#### ATTACHMENTS AVAILABLE

Aerials  Sketch  Maps  Spawning Surveys  Juvenile Trapping  
 Other References

Site id. code: SU2RB2

Site name:

Scale: 1" = 27m

Observer(s): MICHAEL OHS

Legal location: NW 1/4 S13 T33N R10E



CLEAR  
CUT

↑  
SUIATTLE


MIXED  
FOREST


MIXED  
FOREST

53m


108m

219m





20 DEC



SUZ RB2

RM 7.0

NW 4513 T33N R10E

O.F. ENTRY

- REC W TEMP - 41°

- STRM TEMP - 45°

- FLOW 0.1 CFS

- NO ADULT ACCESS &  
JUV. ACCESS IS MARG.

BECAUSE STRM HAS  
TO NEGOTIATE THROUGH

RIVER SILT RECENTLY  
DEPOSITED BY FLOOD

53M WW 1M

- SHALLOW (2"-4"), SLOW  
MOVING STRM.

- BOTTOM HAS LEAVES  
& IS MUD & SILT MIX

- HEAVY W/ BERRY BRUSH

- AQUATIC VEG. IN WATER

108m WW 1m

- @ TOE OF HILL &  
STRM STARTS TO  
PARALLEL IT.

219m WW 1m

- STRM COVERED @  
TIMES W/ FALLEN TREES  
& BRANCHES  
END OF STRM TEMPLE

COMMENTS

WALL GASE STRM THAT  
OFFERS SMALL AMOUNTS  
OF REARING

- GRND WATER SOURCE
- NO SPAWNING
- SEEMED NOT TO BE  
BOTHERED BY FLOOD...

... EXCEPT @ ENTRY

- NO FISH SEEN
- UNSURE IF IT DRIES  
UP DURING SUMMER