

SITE INFORMATION

Site Identifier : SU3LB4	Landowner Type :
Site Name :	Landowner Name :
WRIA : 03.0786X	Address :
Region : NS	Address2 :
Trib to : All Cr	City :
River Mile : 0.20	State :
River System : Suiattle R	Zipcode :
Legal Description : NW1/4S31T33NR11E	Phone :
County : Skagit	
Habitat Type :	

Coordinates
East: 1,772,959.00 **North:** 1,087,243.00

Directions :

Take Forest Service road # 26 up the Suiattle River, turn right at FS # 25 and cross the river then take the next right and follow to the river. Follow river downstream to All Creek and then upstream to site.

Area Overview :

A small, short, low gradient wall-based system with good cover, and good fish use.

Field Survey Information

Date : 1/4/96 **Observer :** Barkdull **Survey Type :** initial

HABITAT INFORMATION

Water Source: () Spring (x) Groundwater () Surface runoff

Flow: (x) Intermittent () Year-round

Estimated Flows (cfs): Lower end: 0.1
Upper end: 0

Water Temperature(C): Lower end: 7
Upper end: 7

Receiving Water Temperature (C): 5

Other Observations:

Site Area Measurements: () Indirect (x) Direct () Combination

Widths: Channel:1.5 Ponds: Wetlands:
 Depths: Channel:0.1 Ponds: Wetlands:
 Total length (includes ponds and wetlands): 60

Total existing habitat area (est. m2): 77

Spawning area:	Mainstem: 6	Tribs:	Total: 6
Impounded area:	Mainstem:	Tribs:	Total:
Other rearing area:	Mainstem: 77	Tribs:	Total: 77
Unaccessible habitat:	Mainstem:	Tribs:	Total:

Spawning habitat conditions: () None () Poor (x) Fair () Good () Exellent

Describe spawning habitat: Small patches of pea gravel

Rearing habitat conditions: None Poor Fair Good Excellent

Describe pond and other rearing habitat: 50/50 pool and riffle, with good cover and woody debris.

Describe unaccessible habitat:

Wetland type: Bog Marsh Scrub-shrub Forested

Describe:

Flooding potential: Low Medium High

Describe: Site lies within the All Creek flood plain and may get flooded on occasion.

FISH INFORMATION

Site entry condition: Poor Fair Good

Describe: Enters at a back-eddy

Coho access and use: Juvenile Unknown None Poor Fair Good
Adult Unknown None Poor Fair Good

Describe: Juveniles were present the day of the survey, the two patches of gravel both had fresh redds.

Other species acces and use: Chum Pink Sockeye Res. Trout Anad trout

Describe: Cutthroat have been observed spawning at the site.

ENHANCEMENT OPPORTUNITIES: None

Project type:

Equipment access:

ADDITIONAL COMMENTS

ATTACHMENTS AVAILABLE

Aerials Sketch Maps Spawning Surveys Juvenile Trapping
 Other References


Site id. code: SU3284


Site name:

Scale: 1" = 20 m.


Observer(s): B. Barkdull

Legal location: NW 1/4 31, T33N, R11E





RM 0.2
NW 1/4



11/4/96 All or springs
0.0 1m Oil CB
2.0 ~~2.0~~ silty Bottom 3
26.0 1m spray a little. More also
2.0m with safe (2/100)
43.0 1m patch good, 1 Bull
patch good to 3
45.0 spring water
60.0 0.5m end
not fluky at all, good water
Cattthroat have been
observed spawning here
Juveniles observed

All or 40°
upper end 44
lower end 44